

China Factory Boningsewing Supplier Corset Busk

-Six color buckles for reference

-Golden, white, black, brozen, silver, [full black](#)/white/siver




Production Flow

-Twice painted made the busk durable and aviod the the water.

-Cutting the length by computer, accruate size gurantee.

CORSET BUSK PRODUCTIVE PROCESS

1. Cut the size as customized



2. Hit the hole



3. Paint and bake



4. Second paint and bake



5. Add bottoms




6. Add the other side bottoms



7. Pack



[Corset-making Accessories](#)



EXHIBITION



FAQ

Q1:Are you an ended manufacture?

A1: Yes, we have our factory

Q2:Why chose Chenyangguang as the supplier ?

- 1.12 years of supplier experience·
- 2.Good quality with best price
- 3.One stop supply. Save your time, save your money

Q3:What about your shipping terms? How long can i get the goods?

1.By sea; By air; Express: DHL, UPS, TNT, EMS, FedEx;

2.In general, the delivery time would be within 2-5 business days.5-7 workdays by express;15-30 workdays by air or by sea.

[CLICK HERE](#)



[BACK TO HOME](#)

[OUR HOME](#)